



## INSPECTIONS ROUTE ORDER (Group by: Assigned Inspectors)

Route Order 1 = 8am - 11am

Route Order 2 = 10am- 2pm

Route Order 3 = 1pm - 4pm

### Alan

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
<a href="#">PMT2024-02122</a>	Foundation, Footing, Setbacks	2	5/6/2026
<a href="#">PMT2025-05550</a>	Final Inspection	2	5/6/2026
<a href="#">PMT2026-01233</a>	Final Inspection	2	5/6/2026
<a href="#">PMT2026-00158</a>	Final Inspection	3	5/6/2026
<a href="#">PMT2025-04392</a>	Underground Conduit	3	5/6/2026
<a href="#">PMT2026-00514</a>	Underground Conduit	3	5/6/2026
<a href="#">PMT2026-00517</a>	Underground Conduit	3	5/6/2026
<a href="#">PMT2026-00518</a>	Underground Conduit	3	5/6/2026
<a href="#">PMT2026-00520</a>	Underground Conduit	3	5/6/2026
<a href="#">PMT2026-00510</a>	Foundation, Footing, Setbacks	3	5/6/2026
<a href="#">PMT2026-00513</a>	Foundation, Footing, Setbacks	3	5/6/2026
<a href="#">PMT2025-04389</a>	Combination	3	5/6/2026
<a href="#">PMT2026-02207</a>	Electrical Utility Clearance (Edison)	3	5/6/2026
<a href="#">PMT2026-02207</a>	Final Inspection	3	5/6/2026
<a href="#">PMT2024-02798</a>	Combination	3	5/6/2026
<a href="#">PMT2024-02798</a>	Drywall, Nailing, Interior Lath	3	5/6/2026
<a href="#">PMT2024-02798</a>	Insulation	3	5/6/2026

### Ryan

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
<a href="#">PMT2026-01730</a>	Electrical Utility Clearance (Edison)	1	5/6/2026
<a href="#">PMT2026-01730</a>	Final Inspection	1	5/6/2026
<a href="#">PMT2026-00807</a>	Final Inspection	1	5/6/2026
<a href="#">PMT2026-01714</a>	Final Inspection	1	5/6/2026
<a href="#">PMT2025-01523</a>	Bonding Grid (Pre-Deck)	1	5/6/2026
<a href="#">PMT2026-00966</a>	Final Inspection	1	5/6/2026
<a href="#">PMT2026-00229</a>	OH Rough/Hydro Inspection	2	5/6/2026
<a href="#">PMT2026-01988</a>	Final Inspection	2	5/6/2026
<a href="#">PMT2025-02675</a>	Underground, Drainage, Floor	2	5/6/2026
<a href="#">PMT2026-00499</a>	Final Inspection	2	5/6/2026
<a href="#">PMT2026-01294</a>	Underground Drainage, Floor	2	5/6/2026
<a href="#">PMT2026-02036</a>	Final Inspection	3	5/6/2026
<a href="#">PMT2026-02066</a>	Final Inspection	3	5/6/2026

### Sebastian

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
<a href="#">PMT2022-03087</a>	Combination	1	5/6/2026
<a href="#">PMT2022-03088</a>	Combination	1	5/6/2026
<a href="#">PMT2025-03918</a>	Framing, Roofing	1	5/6/2026
<a href="#">PMT2026-01640</a>	Final Inspection	1	5/6/2026
<a href="#">PMT2026-02148</a>	Final Inspection	2	5/6/2026

## Sebastian

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
<a href="#">PMT2026-01313</a>	Electrical Utility Clearance (Edison)	2	5/6/2026
<a href="#">PMT2026-01313</a>	Final Inspection	2	5/6/2026
<a href="#">PMT2026-02218</a>	Roof Sheathing, Nailing	2	5/6/2026
<a href="#">PMT2026-01305</a>	Final Inspection	2	5/6/2026
<a href="#">PMT2026-02215</a>	Roof Sheathing, Nailing	2	5/6/2026
<a href="#">PMT2026-02219</a>	Final Inspection	2	5/6/2026
<a href="#">PMT2026-02135</a>	Roof Sheathing, Nailing	3	5/6/2026
<a href="#">PMT2026-01535</a>	Shower/Tub Pan	3	5/6/2026

## Victor

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
<a href="#">PMT2026-01834</a>	Roof Sheathing, Nailing	1	5/6/2026
<a href="#">PMT2026-01258</a>	Bonding Grid (Pre-Deck)	1	5/6/2026
<a href="#">PMT2024-01000</a>	Roof Sheathing, Nailing	1	5/6/2026
<a href="#">PMT2024-01000</a>	Exterior Shear	1	5/6/2026
<a href="#">PMT2026-01801</a>	Final Inspection	1	5/6/2026
<a href="#">PMT2026-01801</a>	Electrical Utility Clearance (Edison)	1	5/6/2026
<a href="#">PMT2026-01943</a>	Final Inspection	1	5/6/2026
<a href="#">PMT2025-05062</a>	Rough Electrical	2	5/6/2026
<a href="#">PMT2017-03842</a>	Combination	2	5/6/2026
<a href="#">PMT2025-04345</a>	Final Inspection	2	5/6/2026
<a href="#">PMT2026-02248</a>	Roof Sheathing, Nailing	2	5/6/2026
<a href="#">PMT2026-00713</a>	OH Rough Inspection	3	5/6/2026
<a href="#">PMT2026-01870</a>	Excavation, Setbacks, Bonding (Pre-Gunite)	3	5/6/2026
<a href="#">PMT2026-01870</a>	Gas Line, Gas Test	3	5/6/2026
<a href="#">PMT2026-01870</a>	Underground	3	5/6/2026